

FITNESS CERTIFICATE

To be filled by the inspecting officer(Asst.Engineer)

Re GO Ms. 20/70/PWD Dt.23-01-1970


- | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--------------|-------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|--|------|-------|--|------|--------------|--------|-----|-------|--|--|-----|---------|-----|-------|--|--|-----|---------|-----|-------|--|------|-----|---------|-----|-------|--|------|-----|---------|-----|-------|--|------|------------|-------|-----|-------|--|------|------------|--------|-----|-------|--|------|
| 1 | Name of officer | PRAMOD M K, ASSISTANT ENGINEER i/c, LID&EW : THRIKKAKARA MUNICIPALITY | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 2 | Name of the School | JAMA -ATH RESIEDNTIAL PUBLIC SCHOOL : PADAMUGAL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 3 | Location with name of Education District/Sub. District | ALUVA SUB DISTRICT | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 4 | Classification of the building as specified in Col.4 of the application for fitness certificate | <table border="0" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;">hight</td> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;">year</td> </tr> <tr> <td>Cellar floor</td> <td>105.70</td> <td>Sqm</td> <td>3.60m</td> <td></td> <td></td> </tr> <tr> <td>G.F</td> <td>1285.80</td> <td>Sqm</td> <td>3.60m</td> <td></td> <td></td> </tr> <tr> <td>F.F</td> <td>1285.80</td> <td>Sqm</td> <td>3.60m</td> <td></td> <td>2010</td> </tr> <tr> <td>S.F</td> <td>1285.80</td> <td>Sqm</td> <td>3.60m</td> <td></td> <td>2010</td> </tr> <tr> <td>T.F</td> <td>1285.80</td> <td>Sqm</td> <td>3.60m</td> <td></td> <td>2010</td> </tr> <tr> <td>Stair room</td> <td>52.90</td> <td>Sqm</td> <td>3.60m</td> <td></td> <td>2010</td> </tr> <tr> <td>Stage roof</td> <td>150.00</td> <td>Sqm</td> <td>4.60m</td> <td></td> <td>2010</td> </tr> </table> | | | | hight | | year | Cellar floor | 105.70 | Sqm | 3.60m | | | G.F | 1285.80 | Sqm | 3.60m | | | F.F | 1285.80 | Sqm | 3.60m | | 2010 | S.F | 1285.80 | Sqm | 3.60m | | 2010 | T.F | 1285.80 | Sqm | 3.60m | | 2010 | Stair room | 52.90 | Sqm | 3.60m | | 2010 | Stage roof | 150.00 | Sqm | 4.60m | | 2010 |
| | | | hight | | year | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Cellar floor | 105.70 | Sqm | 3.60m | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| G.F | 1285.80 | Sqm | 3.60m | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| F.F | 1285.80 | Sqm | 3.60m | | 2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| S.F | 1285.80 | Sqm | 3.60m | | 2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| T.F | 1285.80 | Sqm | 3.60m | | 2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Stair room | 52.90 | Sqm | 3.60m | | 2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Stage roof | 150.00 | Sqm | 4.60m | | 2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 5 | Period for which the certificate is issued | : | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 6 | Nature of defect if any | : Nil | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 7 | a) Foundation and Basement | : RCC Spread footing | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | b) Superstructure | : Column framed structure | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | c) Doors and Window | : Wooden& Built up Steel | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | d) Wood work wrought and put up | : | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | e) Roof | : RCC roof | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | f) Flooring | : Cement floor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | g) Miscellaneous | : | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 8 | Any major defects noticed which will | : Nil | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 9 | Whether the structure is sound or not for conducting classes | : Sound under normal weather condition | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 10 | Whether maintenance works have been done properly | : yes | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |


The stability of the structure should be examined also with reference to lacion ,altitude, intensity of the wir exposure of floor etc. 2. Any additional observation if deemed necessary for the certificate may be furnished separately with this certificate

CERTIFICATE

Certified that the school building was inspected by me on 04/06/2025 and found to be fit/unfit to conduct classes ,for the period 2025-2026 for the reasons stated above.

Place Thrikkakara
Date 05/06/2025




 അസി. എൻജിനീയർ IC
 L.I.D & E.W.
 തൃക്കാക്കര നഗരസഭ